


BnB Motorsports

Bespoke AMT, DCT, SMG transmission parts

<https://www.bnbmotorsports.ca>

Product Images



ADD TO CART

SMG III Position Sensor Rebuild Service



USD \$491.67

NEW replacement BMW SMG III position sensor rebuilt by our technicians to replace frayed wires commonly found on shift position sensor strip. This sensor is located on top of transmission. Common fault codes that can be seen as a result of a failed position sensor are:

- 4F80
- 4F82
- 4F85

This is a normal failure point with the transmission and we highly recommended repairing this if transmission is removed or being repaired for any other type of service. Typical failure modes could be:

- Car stuck in gear
- Erratic shifts
- Transmission not engaging certain gears

This service requires shipping your original sensor to us and typically turnaround is 24 hours to complete.