

## BnB Motorsports

Bespoke AMT, DCT, SMG transmission parts

<https://www.bnbmotorsports.ca>

---

### Product Images



**ADD TO CART**

### HPU pressure sensor 1207002

★★★★★

**CAD \$102.32**

New replacement Ford HPU pressure sensor

A damaged sensor with incorrect pressure readings will make system go into error state and overstress electric motor. The feedback from this sensor is critical to system operation.