

BnB Motorsports

Bespoke AMT, DCT, SMG transmission parts

<https://www.bnbmotorsports.ca>

Product Images



ADD TO CART

Ram ProMaster Shift actuator 68644207AA



CAD \$1,542.73

New OEM replacement Ram ProMaster shift actuator/Shift Fork

Failure of unit will cause system to fail at different shifting scenarios and will trigger error codes that might not directly point to actuator damage. This part is not sold separately from Ram.

Replaces OEM#

- 68644207AA
- 68226914AA
- 68350547AA
- 68375750AA
- 68394415AA
- 68443815AA