

## BnB Motorsports

Bespoke AMT, DCT, SMG transmission parts

<https://www.bnbmotorsports.ca>

---

### Product Images



**ADD TO CART**

## SMG II Clutch Slave Cylinder Position Sensor 21522229841



**CAD \$188.90**

### **We have multiple options to replace or repair Clutch Slave Cylinder Problems.**

Over time the position sensor can start to wear causing incorrect readings to be transmitted to the ECU. This can cause extra stress on pump components and eventually lead to pump failure or error codes associated with clutch control.

This genuine BMW SMG II Clutch Slave Cylinder Position Sensor , featuring the part number 21522229841, is a perfect fit for various BMW models, delivering the performance and reliability expected from the brand. Trust this component to uphold the integrity of your vehicle's transmission system, allowing for a superior driving experience.

Cross Reference

- 21522229841, 21-52-2-229-841, 21 52 2 229 841, 21.52.2.229.841